



ROAD VEHICLE (AND CONTAINER) CERTIFICATION

Company Name: Easy Group Ltd.

Company Address: Easy Bus House.
North Circular Road
West London.
NX10 7XP

1. Licence Number

a) Certificate Number: 31359928

b) Chassis/ID Number: WDF44770323040991/AY15ZKD

1.2. Equipped with a Navigation System: No

1.3. a) Valid only for journeys up to 12 hours in the UK: No

b) Valid for export and journeys over 12 hours in the UK: Yes

1.4. Equipped with securing points for RORO vessels: Yes

2. Types of animals allowed to be transported: Other animals - Domestic Cats and Dogs

3. Total Floor Area: 3.0 M²

a) Top Deck Area: N/A M²

b) Upper Middle Deck Area: N/A M²

c) Lower Middle Deck Area: N/A M²

d) Bottom Deck Area: 3.0 M²

4. Authorisation Valid Until: 15 April 2024

5.1 Body issuing the certificate: Freight Transport Association

5.2 Telephone: 01892 526171

5.3 Fax: 01892 534989


5.4 Email: www.fta.co.uk

5.5 Date: 16 April 2019

5.6 Place: Tunbridge Wells, Kent

5.7 Stamp:

5.8 Signed:



Peter Caffekey

This certificate remains current until the expiry date or withdrawal by DEFRA/Animal welfare

Please keep this certificate in a safe place. Re-issued certificates will be subject to a charge.

The road vehicle and/or container as detailed above has been inspected in accordance with the Welfare in Transport Regulation 1/2005.



Vehicle Body Inspection - Animals other than Domestic Horses, Cattle, Sheep, Goats and Pigs

Company	EasyGroup Ltd
Location	London
Inspection Date	16 Apr 2019 13:15:55
Engineer	Peter Caffekey MSOE MIRTE

Animal Transport Header Information

Asset Type	Van
Registration	AY15ZKD
Chassis Number	WDF44770323040991
Manufacturer	Mercedes-Benz
Model	Vito
Body Type	Livestock Carrier
Year Of Manufacture	2015
Odometer Reading	43283 miles

Date of entry into service	16 Apr 2019
Animal type	domestic cats and dogs
Valid only for journeys up to 12 hours in the UK	No
Top deck stock floor area (square metres)	0
Valid for export and journeys over 12 hours in the UK	Yes
Upper middle deck stock floor area (square metres)	0
Lower middle deck (square metres)	0
Bottom deck stock floor area (square metres)	3
Stock floor area (total in square metres)	3

General Structure - is the vehicle and it's fittings designed, constructed and maintained so as to

Avoid injury and suffering and ensure animal safety	Yes
Protect animals from bad weather, extreme temperatures and adverse climatic changes	Yes
Be cleaned and disinfected	Yes
Prevent animals falling or escaping	Yes
Withstand the stress of vehicle movement	Yes
Provide access for animal inspection and care	Yes
Have anti-slip flooring	Yes
Minimise urine and faeces leakage from flooring	Yes
Have sufficient lighting for inspection and care	Yes
Is the vehicle clearly marked indicating the presence of live animals	Yes
For wild animals and species other than domestic horses, cattle, sheep, goats and pigs is there a notice indicating animals are wild, timid or dangerous	No

Partitions

Are partitions fitted	No
Are the partitions strong enough to withstand weight of animals	No
Are the fittings designed for quick and easy operation	No

Ventilation

Is there a ventilation system	Yes
Can the system ensure appropriate air quality and quantity can be maintained	Yes
Is there sufficient space inside the animal's compartment and at each level to ensure adequate ventilation above the animals when in natural standing position and without hindering natural movement	Yes

Loading/Unloading Equipment

Is suitable loading/unloading equipment carried	Yes
---	-----

Securing Points

Is the vehicle to be used on RO-RO vessels?	Yes
Is the vehicle equipped with suitable securing points for use when in transit on RO-RO vessels	Yes

Outcome of inspection

Inspection Result	Pass
-------------------	------

The road vehicle and/or container as detailed above has been inspected in accordance with the Welfare in Transport Regulation 1/2005. Where applicable any items requiring attention are noted above.

Signature of Engineer:



Engineer: Peter Caffeky MSOE MIRTE

Ref: 31359928